







\emptyset KWIK-CON	d_f [inch]
	
1/4	5/16
3/16	1/4


[inch]	h_1 [inch]	t_{fix} [inch]
1 1/4	1 3/4 - t_{fix}	0...1/4
1 3/4	2 1/4 - t_{fix}	0...3/4
2 1/4	2 3/4 - t_{fix}	0...1 1/4
2 3/4	3 1/4 - t_{fix}	0...1 3/4
3 1/4	3 3/4 - t_{fix}	0...2 1/4
3 3/4	4 1/4 - t_{fix}	0...2 3/4
4	4 1/2 - t_{fix}	0...3




1.1


\emptyset KWIK-CON	$\emptyset d_0$ [inch]		
3/16 inch	3/16 Kwik-Con+ Drill Bits	438630 (TE-C SDS) 438634 (Smooth Shank)	438631 (TE-C SDS) 438635 (Smooth Shank)
1/4 inch	1/4 Kwik-Con+ Drill Bits	438628 (TE-C SDS) 438632 (Smooth Shank)	438629 (TE-C SDS) 438633 (Smooth Shank)







Ø KWIK-CON	df [inch]
	8
6.4	8
4.8	6.5

[mm]	h ₁ [mm]	t _{fix} [mm]
	44 - t _{fix}	0...6
32	44 - t _{fix}	0...6
44	57 - t _{fix}	0...18
44	57 - t _{fix}	0...18
57	70 - t _{fix}	0...31
57	70 - t _{fix}	0...31
70	83 - t _{fix}	0...44
70	83 - t _{fix}	0...44
83	95 - t _{fix}	0...57
83	95 - t _{fix}	0...57
95	108 - t _{fix}	0...69
95	108 - t _{fix}	0...69
102	114 - t _{fix}	0...76
102	114 - t _{fix}	0...76



Ø KWIK-CON			
4.8mm	Kwik-Con+ Drill Bits	438630 (TE-C SDS)	438631 (TE-C SDS)
		438634 (Smooth Shank)	438635 (Smooth Shank)
6.4mm	Kwik-Con+ Drill Bits	438628 (TE-C SDS)	438629 (TE-C SDS)
		438632 (Smooth Shank)	438633 (Smooth Shank)

